FINAL REPORT APRIL 1997

REPORT NO. 96-48

ENVIRONMENTAL MONITORING
OF M1A1 TANKS IN
SOUTH KOREA, HUNGARY, AND
FORT STEWART, GA

19971112 040

Prepared for:

Distribution Unlimited

U.S. Army Armament Research, Development, and Engineering Center
ATTN: AMSTA-AR-QAC-T
Picatinny Arsenal, NJ 07806-5000

MANGOLINE I MILITERIMONIO 4



VALIDATION ENGINEERING DIVISION SAVANNA, ILLINOIS 61074-9639

AVAILABILITY NOTICE

A copy of this report will be furnished each attendee on automatic distribution. Additional copies or authority for reprinting may be obtained by written request from Director, U.S. Army Defense Ammunition Center, ATTN: SIOAC-DEV, Savanna, IL 61074-9639.

DISTRIBUTION INSTRUCTIONS

Destroy this report when no longer needed. Do not return.

Citation of trade names in this report does not constitute an official endorsement.

The information contained herein will not be used for advertising purposes.

UNCLASSIFIED SECURITY CLASSIFICATION OF THIS PAGE

REPORT DOCUMENTATION PAGE								n Approved B No. 0704-0188	
1a. REPORT SEC	CURITY CLASSIFICA	ATION		1b. RESTRICTIVE MARKINGS					
UNCLA	SSIFIED								
2a. SECURITY CLASSIFICATION AUTHORITY				3. DISTRIBUTION / AVAILABILITY OF REPORT					
2b. DECLASSIFIC	CATION / DOWNGRA	UNLIMITED							
4. PERFORMING	ORGANIZATION RI	5. MONITORING ORGANIZATION REPORT NUMBER(S)							
96-48									
6a. NAME OF PERFORMING ORGANIZATION U.S. Army Defense			6b. OFFICE SYMBOL (if applicable)	7a. NAME OF MONITORING ORGANIZATION					
	ition Center		SIOAC-DEV						
	ity, State, and ZIP Co	ode)		7b. ADDRESS (C	ity, State, and ZIP Co	ode)			
	SIOAC-DEV								
Savanna 8a. NAME OF FU ORGANIZAT	, II. 61074-96 nding / sponsori ion	39 NG	8b. OFFICE SYMBOL (if applicable)	9. PROCUREMENT INSTRUMENT IDENTIFICATIO				ON NUMBER	
Defense	Ammunition I	ogistics	AMSTA-AR-AI	-					
Activity	ity, State, and ZIP Co	ado)	AIVISTA-AIX-AI		EUNIDING NUMBER				
oc. ADDRESS (C.	ity, State, and ZIP Co	ode)		PROGRAM	PROJECT NO.	TASK NO).	WORK UNIT	
	AMSTA-AR-A			ELEMENT NO.				ACCESSION NO.	
	y Arsenal, NJ • Security Classificati				<u> </u>			L	
· ·		*	Tamba in Cauth V		ry and Fant Cta	C	٨		
Environi	nental Monito	ning of MIAI	Tanks in South K	corea, Hungar	y, and Fort Ste	wan, G	A		
12. PERSONAL A	UTHOR(S)								
Bradley	J. Haas			T					
13a. TYPE OF RE	PORT	13b. TIME COVER	RED	14. DATE OF REPORT (Year, Month, Day) 15. PAGE COUNT					
Final FROM TO			1997 April						
16. SUPPLEMEN	IARY NOTATION								
17.	COSATI CODES		18. SUBJECT TERMS	(Continue on revers	e if necessary and ide	entify by ble	nck numb		
FIELD	GROUP	SUB-GROUP		(00///100 01/ /0/0/0/	o ii mooddary ama m	onally by ba	JON MANNE	,	
19. ABSTRACT (C	Continue on reverse in	necessary and iden	tify by block number)			· · · · · · · · · · · · · · · · · · ·			
was tasko temperat instrume	ed by U.S. Armure and humid nted in South I	my Armament ity data of the Korea and Hur	nition Center (DA Research, Devel- ammunition stora ngary and six tank tored from June-	opment and E age racks of Mass were instruct	ingineering Cer IIAI tanks. For mented in Ft. S	nter (AI our tank	RDEC)	to obtain	
20. DISTRIBUTIO	N / AVAILABILITY O	F ABSTRACT		21. ABSTRACT S	ECURITY CLASSIFIC	CATION			
XXunclassif	ED/UNLIMITED	UNCLASSIFIED							
	ESPONSIBLE INDIVI		(Include Area Code)	22c. OF	FICE SYMBOL			
<u>JEROMI</u>	EH. KROHN	815-273	-8929		SIO	AC-DEV			

U.S. ARMY DEFENSE AMMUNITION CENTER VALIDATION ENGINEERING DIVISION SAVANNA, IL 61074-9639

REPORT NO. 96-48

ENVIRONMENTAL MONITORING OF M1A1 TANKS IN SOUTH KOREA, HUNGARY, AND FORT STEWART, GA

TABLE OF CONTENTS

PART	PAGE NO.
1. INTRODUCTION	1-1
A. BACKGROUND	1-1
B. AUTHORITY	1-1
C. OBJECTIVE	1-1
D. CONCLUSION	1-1
2. ATTENDEES	2-1
3. TEST PROCEDURES	3-1
4. TEST RESULTS	4-1
5. PHOTOGRAPHS	5-1
6 GRAPHS	6-1

INTRODUCTION

- A. BACKGROUND. The U.S. Army Defense Ammunition Center (DAC), Validation Engineering Division (SIOAC-DEV), was tasked by U.S. Army Armament Research, Development and Engineering Center (ARDEC) to monitor ammunition storage conditions inside M1A1 tanks located in South Korea, Hungary, and Ft. Stewart, GA. This report contains test results of data obtained from June-December 1996.
- B. <u>AUTHORITY</u>. The test was accomplished IAW mission responsibilities delegated by U.S. Army Armament Munitions and Chemical Command (AMCCOM), Rock Island, IL. Reference is made to the following:
- 1. Change 4, 4 October 1974, to AR740-1, 23 April 1973, Storage and Supply Activity Operation.
 - 2. AMCCOM-R, 10-17, Mission and Major Functions of USADACS, 13 January 1986.
- C. <u>OBJECTIVE</u>. The objective of the instrumentation was to obtain temperature and humidity data in the ammunition storage compartments of deployed tanks. U.S. Army Armament Research, Development and Engineering Center will apply the data obtained to provide information concerning chamberability and swelling of two designs of bourrelets.
- D. <u>CONCLUSION</u>. The temperature and humidity in the stowage compartments of the tanks generally maintained higher temperature levels than ambient conditions provided. The temperature and humidity conditions of the semiready and ready storage compartments were similar. Hull storage experienced similar temperature conditions to the semiready and ready storage areas. The standing water, being common in the hull storage area, contributed to the generally higher hull storage area humidity than the semiready and ready storage areas.

JUNE - DECEMBER 1996

ATTENDEES

Director Bradley J. Haas

Mechanical Engineer U.S Army Defense Ammunition Center

DSN 585-8336 ATTN: SIOAC-DEV 815-273-8336 3700 Army Depot Road Savanna, IL 61074-9639

William R. Meyer Director

General Engineer U.S Army Defense Ammunition Center

ATTN: SIOAC-DEV DSN 585-8090 815-273-8090 3700 Army Depot Road Savanna, IL 61074-9639

Quinn D. Hartman Director

General Engineer U.S. Army Defense Ammunition Center

DSN 585-8992 ATTN: SIOAC-DEV 815-273-8992 3700 Army Depot Road Savanna, IL 61074-9639

David V. Valant Director

Electronics Technician U.S. Army Defense Ammunition Center

DSN 585-8988 ATTN: SIOAC-DEV 815-273-8988 3700 Army Depot Road Savanna, IL 61074-9639

Richard O. Schubert Commander

201-724-3519

DSN 880-7597 U.S. Army Armament Research, Development

201-724-7597 and Engineering Center

> ATTN: AMSTA-AR-QAC-T, B-62 Picatinny Arsenal, NJ 07806-5000

MAJ Steve Thorsen Office of Project Manager for DSN 880-3519 Tank Main Armament Systems

ATTN: AMCPM-TMA Picatinny Arsenal, NJ 07806-5000 Christopher A. DeLima DSN 880-3782 201-724-3782

Commander
U.S. Army Armament Research, Development and Engineering Center
ATTN: AMSTA-AR-QAC-T
Picatinny Arsenal, NJ 07806-5000

TEST PROCEDURE

M1A1 tanks were instrumented at the following three sites: Fort Stewart, GA; Taborfalva Training Area, Hungary; and Camp Gary Owen, South Korea. Each tank was instrumented with three ACR data loggers. One data logger was placed in the tank ready rack, one data logger in the semiready rack, and one data logger in the hull stowage compartment. These data loggers collected temperature and humidity readings for these locations. The instrumented tanks continued to be used in normal operations, including maintenance. Additionally, a weather station was assembled at each location to record ambient conditions.

At the Fort Stewart site, six tanks were instrumented as described above. Readings were recorded every 10 minutes, 30 May - 1 November 1996. A weather station was operated onsite.

At Taborfalva Training Area, Hungary, four tanks were instrumented as described above. The data loggers recorded readings every 10 minutes. The initial data loggers were installed 24 June 1996. The program concluded 16 December 1996. A weather station was operated onsite.

The South Korea site had four tanks instrumented, each with three data loggers. Camp Gary Owen is located approximately 50 km east-northeast of Seoul and 325 km north of Taegu. The data loggers recorded temperature and humidity data every 30 minutes. The data loggers were initially installed 6 June 1996, with the program concluding 20 December 1996. The South Korea weather station was positioned at Ammunition Depot 2 (AD-2), located approximately 40 km southeast of Taegu.

TEST RESULTS

Six M1A1 tanks were instrumented at Fort Stewart from 30 May - 31 October 1996. The ambient temperature during this timeframe ranged from 44 degrees Fahrenheit to 101 degrees Fahrenheit. The maximum semiready storage temperature of 112 degrees Fahrenheit was recorded in tank 206 on 23 June 1996. The maximum ready storage temperature recorded was 117 degrees Fahrenheit in tank 224 on 23 June 1996. The maximum hull storage temperature recorded was 108 degrees Fahrenheit in tank 206 on 24 June 1996 and tank 221 on 10 July 1996 (see part 6 for additional temperature data obtained at Fort Stewart).

The ambient humidity at Fort Stewart ranged from 14 to 100 percent. Readings of 100 percent were obtained during each month. Hull storage readings ranged from 37 to 100 percent, with the hull storage of five of the six tanks reaching 100 percent humidity. The remaining tank, tank 210, had a maximum hull storage humidity reading of 83 percent.

Tank 210 was the only instrumented tank that did not show evidence of standing water in the hull storage area. Semiready storage readings ranged from 21 to 100 percent, with four of the six instrumented tanks reaching 100 percent humidity. The remaining tanks, tanks 210 and 213, had maximum ready storage readings of 88 and 83 percent, respectively. Ready storage humidity readings ranged from 29 to 100 percent, with three of the six instrumented tanks reaching 100 percent humidity. The remaining three tanks (tanks 210, 213, and 219) had maximum humidity readings of 79, 93, and 90 percent, respectively. No standing water was noted in the semiready or ready storage areas of any of the instrumented tanks (for additional humidity distribution data, see part 6).

From 24 June - 16 December 1996, four M1A1 tanks were instrumented at Taborfalva Training Area, Hungary. During this timeframe, the ambient temperature ranged from

20 degrees Fahrenheit to 93 degrees Fahrenheit. The maximum semiready storage temperature reading of 98 degrees Fahrenheit was recorded in tank 301 on 8 July 1996. The maximum ready storage temperature of 107 degrees Fahrenheit was also recorded in tank 301 on 8 July 1996. The maximum recorded hull storage temperature of 105 degrees Fahrenheit occurred in tank 301 on 4 July 1996.

The ambient humidity at Taborfalva Training Area ranged from 20 to 100 percent.


Readings of 100 percent were obtained during each month of instrumentation. Hull storage readings ranged from 36 to 100 percent with three of the four instrumented tanks recording maximum readings of 100 percent. The remaining tank, tank 304, had a maximum recorded reading of 93 percent. Semiready storage readings ranged from 36 to 100 percent with the semiready storage of each instrumented tank reaching 100 percent for a period of time. The ready storage humidity readings ranged from 34 to 100 percent, with only tank 312 reaching 100 percent humidity. Each of the remaining three instrumented tanks had maximum humidity readings in the ready storage area in excess of 75 percent. Additional details for the temperature and humidity data obtained in Hungary are located in part 6.

From 27 June - 20 August 1996, three M1A1 tanks at Camp Gary Owen, South Korea were each equipped with three data loggers. This timeframe is referred to as "Setup No. 1." Instead of replacing the removed data loggers, four sets of three data loggers were placed in four different M1A1 tanks, referred to as "Setup No. 2." Monitoring of these four tanks continued until the termination of the program on 18 December 1996. No ambient conditions at this location were obtained during this timeframe. Ambient conditions from AD-2 were used for data analysis. During this timeframe, ambient temperature conditions ranged from 14 to 100 degrees Fahrenheit. The maximum semiready storage temperature reading was 110 degrees Fahrenheit in tank A-42 on 1 August 1996. The maximum ready storage temperature was


104 degrees Fahrenheit in tank C-33 on 21 August 1996. The maximum hull storage temperature was 104 degrees Fahrenheit in tank C-33 on 21 August 1996.

The ambient humidity at AD-2 ranged from 15 to 100 percent. Readings of 100 percent were obtained during each month of instrumentation. Hull storage readings ranged from 33 to 100 percent with three of the four instrumented tanks in Setup No. 2 having readings of 100 percent. The remaining tank, tank A-14, had a maximum hull storage humidity reading of 76 percent. Semiready storage humidity readings ranged from 36 to 90 percent, with the semiready storage of six of the seven tanks that were instrumented providing readings in excess of 78 percent at a period of time. The ready storage humidity readings ranged from 28 to 98 percent, with the minimum peak humidity reading of any instrumented tank being 79 percent. Additional details for the temperature and humidity data obtained in South Korea are located in part 6.

PHOTOGRAPHS



U.S. ARMY DEFESE AMMUNITION CENTER




U.S. ARMY DEFESE AMMUNITION CENTER

PHOTO NO. AO317-SCN-96-155-3043. This photograph shows an ACR data logger located in the semiready rack of an M1A1 tank.



U.S. ARMY DEFESE AMMUNITION CENTER

PHOTO NO. AO317-SCN-96-155-3045. This photograph shows the ready rack of an M1A1 tank. An ACR data logger is located in the top right of the compartment.



U.S. ARMY DEFESE AMMUNITION CENTER

PHOTO NO. A0317-SCN-96-155-3040. This photograph shows an ACR data logger located in the hull rack of an M1A1 tank.




PHOTO NO. AO317-SCN-96-155-3055. This photograph shows the weather station installed at Fort Stewart. U.S. ARMY DEFESE AMMUNITION CENTER


GRAPHS

FORT STEWART DATA


FT. STEWART M1A1 TANK MONITORING DATA

AMBIENT	JUNE	JULY	AUGUST	SEPTEMBER	OCTOBER
High Temperature	101	101	96	96	89
Low Temperature	60	71	68	58	44
High Humidity	100	100	100	100	100
Low Humidity TANK 206	23	26	28	15	14
SEMIREADY High Temperature Low Temperature High Humidity Low Humidity	112	102	96	103	101
	68	76	76	72	56
	94	68	61	100	81
	32	45	47	52	57
READY High Temperature Low Temperature High Humidity Low Humidity	115	117	111	97	98
	68	75	75	72	55
	92	63	55	100	100
	31	42	44	52	90
HULL High Temperature Low Temperature High Humidity Low Humidity	108	98	98	95	89
	64	77	76	70	56
	100	100	100	100	65
	50	65	79	45	45
TANK 210 SEMIREADY High Temperature Low Temperature High Humidity Low Humidity	108	100	NA	96	87
	69	85	NA	77	60
	81	67	NA	87	88
	36	61	NA	77	63
READY High Temperature Low Temperature High Humidity Low Humidity HULL	116	113	108	110	94
	61	75	73	72	55
	79	60	55	55	55
	29	42	43	43	43
High Temperature	106	99	89	89	85
Low Temperature	70	77	74	73	56
High Humidity	50	83	80	80	57
Low Humidity	37	42	74	49	49
TANK 213 SEMIREADY High Temperature Low Temperature High Humidity Low Humidity	98	101	93	89	84
	69	77	75	72	55
	81	83	84	88	87
	60	62	70	51	44
READY High Temperature Low Temperature High Humidity Low Humidity HULL	107	113	104	98	92
	69	76	73	68	54
	83	67	61	93	78
	54	37	40	66	58
High Temperature	107	107	107	101	87
Low Temperature	69	84	78	70	55
High Humidity	100	100	87	100	100
Low Humidity	86	53	84	75	87
TANK 219 SEMIREADY High Temperature Low Temperature High Humidity Low Humidity	101	104	97	104	93
	68	75	74	70	55
	100	85	90	92	83
	47	55	69	49	55
READY High Temperature Low Temperature High Humidity Low Humidity HULL	111	112	NA	108	93
	71	85	NA	70	56
	90	67	NA	88	77
	39	38	NA	57	55
High Temperature Low Temperature High Humidity Low Humidity	101 71 100 84	93 82 100 52	NA NA NA	98 69 100 66	84 54 97 64
TANK 221 SEMIREADY High Temperature Low Temperature High Humidity Low Humidity	99	104	95	95	85
	69	77	74	72	58
	100	95	59	92	92
	40	45	42	31	21
READY High Temperature Low Temperature High Humidity Low Humidity	111	116	103	110	98
	68	70	75	70	57
	100	100	94	100	84
	42	44	49	39	39
HULL High Temperature Low Temperature High Humidity Low Humidity	98	108	93	92	97
	70	76	75	73	65
	97	100	100	100	100
	59	85	94	54	74
TANK 224 SEMIREADY High Temperature Low Temperature High Humidity Low Humidity	102	90	NA	95	85
	69	85	NA	68	54
	100	50	49	100	100
	73	44	44	43	69
READY High Temperature Low Temperature High Humidity Low Humidity	117	109	110	102	94
	70	75	73	68	53
	100	94	92	90	85
	64	71	69	75	68
HULL High Temperature Low Temperature High Humidity Low Humidity	93	106	88	81	NA
	70	76	74	73	NA
	97	97	97	100	NA
	59	56	84	94	NA

1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 206




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 206




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 206







1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 206




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 206




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 206




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 206




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 206




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 210







1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 210




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 210




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 210




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 210




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 210




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 210




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 210




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 213




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 213







1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 213




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 213




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 213




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 213




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 213




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 219




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 219




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 219




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 219




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 219




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 219




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 219




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 219




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 221




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 221




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 221







1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 221




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 221




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 221




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 221



1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 221




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 224




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 224






1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 224







1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 224




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 224




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 224





1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 224




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 224










Number of Occurances




Humidity









EEE Semiready

90-100

70-80 Humidity

60-70

50-60

40-50

200

1500 1000


Number of Occurences


2500 2000


3000


Ambient

Ft. Stewart, Tank 224 September, 1996









cas Semiready cas Ready cas Hull

9

90-100

80-90

70-80 Humidity

60-70

50-60

40-50

500

Ambient Ambient

Ft. Stewart, Tank 219

September, 1996


2500

2000

1500

8

Number of Occurences



Ess Semiready Ess Ready ES Hull

100

Ambient

Ran Ambient
Est Semiready
Ran Ready

CO Hull

en Semiteady


100

m Ambient


HUNGARY DATA

HUNGARY M1A1 TANK MONITORING DATA


AMBIENT High Temperature Low Temperature High Humidity	JUNE NA NA NA	JULY 93 42 100	AUGUST 90 45 100	SEPTEMBER 74 36 100	72 24 100	NOVEMBER 70 24 100	DECEMBER 47 20 100
Low Humidity TANK 301	NA	25	20	37	38	34	59
SEMIREADY High Temperature	88	98	94	77	70	64	46
Low Temperature	60	58	59	46	37	31	30
High Humidity Low Humidity	100 54	100 85	100 36	100 56	100 52	67 53	66 55
READY							
High Temperature Low Temperature	89 60	107 57	101 58	81 45	75 35	63 31	51 30
High Humidity	94	95	96		75	76	76
Low Humidity HULL	47	59	35	51	52	57	56
High Temperature	77	105	98	93	83	64	57
Low Temperature	63 100	60 100	62 100	49 100	35 100	34 68	31 69
High Humidity Low Humidity	47	76	36	94	59	58	55
TANK 304 SEMIREADY				•			
High Temperature	89	95	93	79	72	63	44
Low Temperature High Humidity	60 100	58 100	58 100	48 75	37 70	33 63	28 59
Low Humidity READY	52	69	43	49	50	49	49
High Temperature Low Temperature	93 59	102 57	101 57	85 48	74 37	77 34	52 29
High Humidity	92	94	95	84	70	62	62
Low Humidity HULL	52	71	49	43	43	41	48
High Temperature	98	89	96	87	77	58	52
Low Temperature High Humidity	63 91	60 90	58 88	48 73	39 73	34 65	29 65
Low Humidity	48	76	46	48	51	50	51
TANK 306 SEMIREADY							
High Temperature	83	94	91	76	74	65	45
Low Temperature High Humidity	60 61	58 6 5	59 67	48 66	36 73	33 83	27 75
Low Humidity	51	52	39	45	46	47	33
READY High Temperature	89	104	97	83	77	70	46
Low Temperature	59	57	59	47	34	31	27
High Humidity Low Humidity	59 47	62 44	67 40	65 42	78 41	83 40	81 51
HULL							
High Temperature Low Temperature	83 63	100 62	104 68	89 53	80 35	75 34	57 29
High Humidity	100	100	100	100	100	94	92
Low Humidity	50	81	37	61	68	84	85
TANK 312							
SEMIREADY High Temperature	89	95	94	81	74	67	44
Low Temperature	59	58 00	58 100	46 79	39 97	29 94	28 92
High Humidity Low Humidity	99 31	99 59	35	53	54	70	70
READY	01	00	100	82	76	66	42
High Temperature Low Temperature	91 60	99 56	100 56	46	36	66 29	27
High Humidity Low Humidity	94 48	100 54	97 34	82 50	100 46	97 62	94 73
HULL	40						
High Temperature Low Temperature	94 64	93 60	102 59	97 56	89 38	73 32	42 29
High Humidity	100	100	100	100	100	100	100
Low Humidity	47	89	37	67	51	90	94


























Taborfalva Training Area, Hungary 1996 M1A1 Tank Evaluation
























































Taborfalva Training Area, Hungary Tank 306 1996 M1A1 Tank Evaluation














































Ra Ambient
Semiready
Ra Ready

2

Thousands

Number of Occurences

90-100


70-80 80-90 Humidity


60-70


50-60

0

Hungary, Tank 306








Thousands


Number of Occurences


⊞ Semiready ⊞ Ready ⊞ Hull

88 Ambient

Hungary, Tank 306 August, 1996










Ambient C. Semiready

rs Ready C: Hull







spuesnoul

Number of Occurences

≅ Semiready


to Ready ⊞ Hull


> 30-40 40-50 50-60 60-70 70-80 80-90 90-10 Humidity


88 Ambient


Hungary, Tank 306 October, 1996

J.









1000

Number of Occurences

1500

500

 Semiready ඎ Ready Hull

> 70-80 80-90 Humidity

02-09


20-60


™ Ambient

Hungary, Tank 306

December, 1996

2000






SOUTH KOREA SETUP NO. 1 DATA


SOUTH KOREA M1A1 TANK MONITORING DATA SETUP #1 (JUNE 27 - AUGUST 20)

High Humidity 100 100 10 Low Humidity 70 45 2 TANK A-24 SEMIREADY	00 66 00 28
Low Temperature 61 59 6 High Humidity 100 100 10 Low Humidity 70 45 2 TANK A-24 SEMIREADY High Temperature 75 83 9	66 00 28
High Humidity 100 100 10 Low Humidity 70 45 2 TANK A-24 SEMIREADY High Temperature 75 83 9	00 28 93
Low Humidity 70 45 2 TANK A-24 SEMIREADY High Temperature 75 83 9	28
TANK A-24 SEMIREADY High Temperature 75 83 9	3
SEMIREADY High Temperature 75 83 9	
SEMIREADY High Temperature 75 83 9	
High Temperature 75 83 9	
· · · · · · · · · · · · · · · · · · ·	
LOW Lettiperature on on on o	M
men i emperatione	90
	78
Low Humidity 85 72 7 READY	•
	4
9	35
—	88
	7
	′
HULL	
High Temperature NA NA NA	
Low Temperature NA NA NA	
High Humidity NA NA NA	
Low Humidity NA NA NA	Α
TANK A-42	
SEMIREADY	
High Temperature 80 97 11	0
	33
High Humidity 54 58 NA	
Low Humidity 46 48 NA	
READY	•
High Temperature NA NA NA	Α
Low Temperature NA NA NA	
High Humidity NA NA NA	
Low Humidity NA NA NA	
HULL	•
	1
	31
High Humidity 59 63 N	
Low Humidity 56 51 N	
Low Hammary 30 CT 1.	
TANK A-44	
SEMIREADY	
High Temperature 75 87 10	13
= - · · · · · · · · · · · · · · · · · ·	33
High Humidity 60 64 N	
Low Humidity 51 53 N	Α
READY	
High Temperature NA NA NA	
= · · · · · · · · · · · · · · · · ·	Α
	ΙΑ
Low Humidity NA NA N	IΑ
HULL	
High Temperature 79 87 10	
==== · · · · · · ·	33
•	IΑ
Low Humidity 56 56 N	Α


1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank A-24





1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank A-24




1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank A-24










1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank A-42





1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank A-42
















1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank A-44







SOUTH KOREA SETUP NO. 2 DATA


SOUTH KOREA M1A1 TANK MONITORING DATA SETUP #2 (AUGUST 20 - DECEMBER 18)

AMBIENT High Temperature Low Temperature High Humidity Low Humidity	AUGUST	SEPTEMBER	OCTOBER	NOVEMBER	DECEMBER
	97	87	80	67	59
	63	48	29	20	14
	100	100	100	100	100
	33	30	15	19	24
TANK A-14 SEMIREADY High Temperature Low Temperature High Humidity Low Humidity READY	94	82	90	58	63
	65	68	38	24	15
	54	53	77	87	66
	45	46	37	50	35
High Temperature Low Temperature High Humidity Low Humidity HULL	96	83	85	58	63
	65	68	38	26	15
	52	50	60	80	64
	43	46	35	50	31
High Temperature	95	81	83	65	67
Low Temperature	65	70	40	27	16
High Humidity	71	76	67	70	70
Low Humidity	49	63	33	53	32
TANK B-11 SEMIREADY High Temperature Low Temperature High Humidity Low Humidity	96	83	83	NA	NA
	65	70	50	NA	NA
	62	62	61	NA	NA
	45	50	43	NA	NA
READY High Temperature Low Temperature High Humidity Low Humidity HULL	96	83	79	60	64
	65	70	49	23	14
	61	60	66	98	72
	44	49	40	53	29
High Temperature Low Temperature High Humidity Low Humidity	97	73	93	65	67
	66	68	44	27	16
	81	72	100	100	92
	44	46	43	69	37
TANK C-33 SEMIREADY High Temperature Low Temperature High Humidity Low Humidity	102	90	79	60	64
	65	68	40	23	14
	75	73	76	79	56
	40	51	36	44	34
READY High Temperature Low Temperature High Humidity Low Humidity HULL	104	94	84	60	65
	65	68	38	23	14
	80	75	76	75	64
	44	51	39	44	28
High Temperature	104	85	81	NA	NA
Low Temperature	67	69	47	NA	NA
High Humidity	100	100	100	NA	NA
Low Humidity	42	92	39	NA	NA
TANK D-31 SEMIREADY High Temperature Low Temperature High Humidity Low Humidity	96 68 54 46	98 70 78 50	82 40 81 42	61 24 62 39	54 15 62 42
READY High Temperature Low Temperature High Humidity Low Humidity	97	94	93	60	54
	65	72	38	21	13
	79	52	76	76	66
	44	44	36	49	48
HULL High Temperature Low Temperature High Humidity Low Humidity	94	91	82	67	72
	65	70	41	29	19
	53	53	100	100	92
	45	45	39	71	47





1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank A-14







1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank A-14








1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank A-14













Semi-Ready


Ready

= H


Ambient









1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank B-11




1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank B-11




1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank B-11







1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank C-33




1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank C-33







1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank C-33





1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank C-33







1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank C-33












1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank D-31







1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank D-31





1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank D-31





1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank D-31
































(